



**Photo 1**


View of south and west sides of Office Building. Roof of Central Unit in foreground. Tar covered exhaust hood in center of photo.



**Photo 2**

View of duct work on roof of Building 12.





**Photo 3**


Asbestos caulking on exterior wide flange columns. North side of Building 50.



**Photo 4**

Mudded pipe fitting. Center of Building 7.





**Photo 5**

Door and window frames with asbestos caulking. North side of Building 9.



**Photo 6**

Asbestos caulking on copper flashing and at base of wide flange beam. Lower roof on south side of Building 50.